



SET UP – WYMIARY


K 1/2/3N




K 1/2/3N P30 LUX




STL



SHD



SHM



SSK

